# TROPICAL ATMOSPHERE-OCEAN (TAO) PROGRAM FINAL CRUISE REPORT

KA-09-05

Area: Equatorial Pacific between 8°N and 8°S latitude along 155°W Longitude, 8°S to 8°N

Latitude along 170°W Longitude and 8°N and 8°S latitude along 180° Longitude.

**Itinerary**:

KA-09-05 DEP November 9, 2009, Honolulu, HI

ARR December 6, 2009, Honolulu, HI

#### **CRUISE DESCRIPTION**

The Tropical Atmosphere Ocean (TAO) array consists of 70 buoys utilizing a taut line mooring configuration used to mount data collection sensors for climate research purposes. Fifteen buoys are serviced by JAMSTEC and the remaining 55 buoys from 95°W longitude to 165°E longitude are serviced by National Data Buoy Center (NDBC). Repair and maintenance of the buoys is performed by NDBC contracted personnel on an annual basis utilizing the NOAA Ship *Ka'imimoana* and other ships. The buoys' deployment lifecycle are up to 18 months to ensure at least one year of data collection can be completed.

### TAO Project Points of Contact:

TAO Program Manager TAO Operations Manager

Shannon McArthur Lex LeBlanc

National Data Buoy Center National Data Buoy Center

Building 1007 Building 3203

Stennis Space Center, MS 39529 Stennis Space Center, MS 39529

228-688-2830 228-688-7465

Email: shannon.mcarthur@noaa.gov Email: lex.leblanc@noaa.gov

## TAO Cruise Objective and Plan:

The objective of this cruise was the maintenance of the TAO Array along the 155°W, the 170°W meridian and the 180°.

The scientific complement for the cruise embarked at *Honolulu*, *HI* on *November 8*, 2009. The ship departed on *November 9*, 2009 and conducted operations as listed in Section 2.1. NOAA Ship *Ka'imimoana* arrived in *Honolulu*, *HI* on *December 6*, 2009.

#### 1.0 **PERSONNEL**

# 1.1 *CRUISE LEAD AND PARTICIPATING SCIENTISTS*:

Cruise Lead: Aaron Boutwell

### Participating Scientists:

Name	Gender	Nationality	Affiliation
Aaron Boutwell	M	US	NOAA/NDBC
James Rauch	M	US	NOAA/NDBC
Alan Lossett	M	US	NOAA/NDBC

#### 2.0 **OPERATIONS**

# 2.1 <u>TAO Data Recovery Summary</u>

Mooring Operations conducted are shown in the tables below. The following provides details on the data recovery efforts for the buoys serviced. All noted time in the summary reports is Coordinated Universal Time (UTC):

# **Cruise Summary**

Buoy Site: 5N 180W	Mooring Depth: 5212 m	
Mooring Operation: Repair	Mooring ID#: PM778B	
<b>Deployed Location:</b> 04 59.0N 179.53.7W	Deployed Date: 9/23/2008	
<b>Repair Location:</b> 05 00.3N 179.53.8W	Repaired Date: 11/17/2009	
Sensors/Equipment Lost at Sea: None		
Sensors Damaged/Fouled: N/A		
Fishing Vandalism: 1/2 inch line attached to tower leg		
Sensors/Tubes Not Downloaded: Data logger tube downloaded successfully.		

<b>General Comments:</b> T	eam Preformed a Tube Swap		
Site Sensor Failures	<b>Date Sensors Failed</b>	Why	Field Service
		Sensors	Observations
		Failed	
Tube	10/19/2009	Not	Buoy was on station
		transmitting	but tube was not
			transmitting.

<b>Buoy Site: 2N 180W</b>		Mooring De	<b>pth:</b> 5446m		
<b>Mooring Operation: </b> \	Visit Visit	Mooring ID	#: PM776B		
<b>Deployed Location: 02</b>	2 00.93N 179 47.61W	Deployed Da	ate: 06/30/2009		
<b>Repair Location:</b> 02 0	1.5N 179 49.0W	Repaired Da	ate: 11/18/2009		
Sensors/Equipment L	ost at Sea: None				
Sensors Damaged/Fou	lled: None				
Fishing Vandalism: N	one.				
Sensors/Tubes Not Do	wnloaded: None				
<b>General Comments: N</b>	To damage on buoy and riding well	in water			
Site Sensor Failures	Site Sensor Failures Date Sensors Failed Why Field Service				
		Sensors	<b>Observations</b>		
		Failed			

Buoy Site: 0 180W	Mooring Depth: 5393m	
Mooring Operation: Deployment	Mooring ID#: PM864A	
<b>Deployed Location:</b> 00 01.375N 179 54.41W	<b>Deployed Date:</b> 11/18/2009	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: None		

Buoy Site: 2S 180W	Mooring Depth: 5338m	
<b>Mooring Operation:</b> Recovery	Mooring ID#: PM827A	
<b>Deployed Location:</b> 01 59.5S 179 53.3W	<b>Deployed Date:</b> 06/29/2009	
Recovered Location: None	Recovered Date: 11/19/2009	
Previous Repair Date: None		
Sensors/Equipment Lost at Sea: NDBC Equipm	ent: Buoy: THN-016 Release SN# 020991	
PMEL Equipment: tube:529 AT/RH:34267 Wind:63920 SSC:14328 T1:13519 T2:13520		
T3:13521 T4:13524 T5:13833 T6:14690 T7:13	691 T8:14692 T9:14763 T10:14764	
Sensors Damaged/Fouled: N/A		
Fishing/Vandalism: Buoy Lost at Sea.		
Sensors/Tubes Downloaded: None		
General Comments: Buoy Lost at Sea.		

Site Sensor Failures	Date Sensors Failed	Why Sensors Failed	Field Service Observations
Tube	7/28/2009	Not transmitting.	None

Buoy Site: 2S 180W	<b>Mooring Depth:</b> 5367m	
Mooring Operation: Deployment	Mooring ID#: PM865A	
<b>Deployed Location:</b> 02 00.1S 179 55.0E	<b>Deployed Date:</b> 11/19/2009	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: None		

<b>Buoy Site:</b> 8S 170W		Mooring Dep	oth: 5374m		
<b>Mooring Operation: \</b>	/isit	Mooring ID#	: PM815A		
<b>Deployed Location: 08</b>	3 00.2S 170 00.4W	Deployed Da	te: 05/28/2009		
<b>Repair Location:</b> 07 5	8.5S 170 01.6W	Repaired Da	te: 11/22/2009		
Sensors/Equipment L	ost at Sea: None	·			
Sensors Damaged/Fou	<b>lled:</b> Tube not transmitting				
Fishing Vandalism: N	one.				
Sensors/Tubes Not Do	wnloaded: None				
<b>General Comments:</b> N	To damage on buoy and riding well	l in water			
Site Sensor Failures	Site Sensor Failures Date Sensors Failed Why Field Service				
		Sensors	<b>Observations</b>		
		Failed			

<b>Buoy Site:</b> 5S 170W R	efresh	Mooring Do	e <b>pth:</b> 5418m	
<b>Mooring Operation:</b> R	Mooring Operation: Repair Mooring ID#: DM001B			
<b>Deployed Location:</b> 04 58.3S 169 57.1W <b>Deployed Date:</b> 05/29/2009			ate: 05/29/2009	
<b>Repair Location:</b> 04 5	8.3S 169 57.1W	Repaired D	ate: 11/23/2009	
Sensors/Equipment Lo	ost at Sea: None			
Sensors Damaged/Fou	<b>led:</b> Tube not transmitting			
Fishing Vandalism: N	one			
Sensors/Tubes Not Downloaded: Tube not down loaded				
General Comments: Team Preformed a Tube Swap				
Site Sensor Failures	Site Sensor Failures Date Sensors Failed Why Field Service			
	Sensors Observations			
	Failed			
Tube	10/23/2009	Not	Buoy was on station	
		tranmitting	but tube was not	

	transmitting

<b>Buoy Site:</b> 5S 170W		Mooring Depth: 5396m	
<b>Mooring Operation: </b> \	<sup>7</sup> isit	Mooring ID#	: PM816A
<b>Deployed Location: 05</b>	5 00.0S 169 59.5W	Deployed Da	te: 05/30/2009
<b>Repair Location:</b> 4 59	.9S 170 01.2W	Repaired Da	te: 11/23/2009
Sensors/Equipment Lo	ost at Sea: None		
Sensors Damaged/Fou	led: None		
Fishing Vandalism: N	one.		
Sensors/Tubes Not Do	wnloaded: None		
<b>General Comments: N</b>	To damage on buoy and riding we	ll in water	
Site Sensor Failures	Date Sensors Failed	Why	Field Service
		Sensors	<b>Observations</b>
		Failed	

<b>Buoy Site:</b> 8S 155W		Mooring Depth: N/A		
<b>Mooring Operation: R</b>	Recovery	Mooring ID#: PM814A		
<b>Deployed Location:</b> 0	8 15.730S 154 59.550W	Deployed Date: 5/16/	/2009	
<b>Recovered Location:</b> (	08 39.2S 159 41.9W	Recovered Date: 11/26/2009		
<b>Previous Repair Date:</b>	None			
Sensors/Equipment Lo	ost at Sea: Release SN#	33044, PMEL T10 Senor	SN# 13816	
Sensors Damaged/Fou	iled: None			
Fishing/Vandalism: N	Vone			
Sensors/Tubes Downlo	oaded: Tube and all sub	surface sensors download	ed except, T10, T3	
was downloaded but los	st its data during the proc	ess.		
<b>General Comments: N</b>	Vilspin was parted at abou	ıt 425 m.		
Site Sensor Failures	Date Sensors Failed	Why Sensors Failed	Field Service Observations	

Buoy Site: 8S 155W	Mooring Depth: 5338m	
Mooring Operation: Deployment	Mooring ID#: PM814B	
<b>Deployed Location:</b> 08 15.426S 154 59.537W	Deployed Date:11/29/2009	
Pre-Deployment On Deck Instrument Failures: SSC was not reporting any data, T3 was		
acting strange during the data down load and could not be trusted to redeploy.		
Sensors/Equipment Lost at Sea: Release SN# 025943		
Sensors Damaged During Deployment: None		
<b>General Comments:</b> upon deployment the mooring failed in the 7 <sup>th</sup> spool of nylon and was		
adrift. We recovered the buoy once more and redeployed. This failure is the cause of the lost		
release.		

<b>Buoy Site:</b> 5S 155W		Mooring De	<b>pth:</b> 4982m
Mooring Operation: Visit		Mooring ID#: PM760A	
<b>Deployed Location:</b> 04 59.395S 154 58.286W		<b>Deployed Date:</b> 08/17/2008	
<b>Repair Location:</b> 4 59.708S 154 59.817W		Repaired Date: 11-29-2009	
Sensors/Equipment Lost at Sea: None			
Sensors Damaged/Fouled: None			
Fishing Vandalism: None.			
Sensors/Tubes Not Downloaded: None			
General Comments: No damage on buoy and riding well in water			
Site Sensor Failures	Date Sensors Failed	Why	Field Service
		Sensors	<b>Observations</b>
		Failed	

Buoy Site: 00 155W		Mooring Depth: 4174m		
<b>Mooring Operation:</b> Visit		Mooring ID	Mooring ID#: PM758A	
<b>Deployed Location:</b> 00 00.632N 154 58.197W		<b>Deployed Date:</b> 08/15/2008		
<b>Repair Location:</b> 00 0	1.172S 154 58.232W	Repaired Date: 12-1-2009		
Sensors/Equipment Lo	ost at Sea: None			
Sensors Damaged/Fou	led: None			
Fishing Vandalism: No	one.			
Sensors/Tubes Not Do	wnloaded: None			
<b>General Comments:</b> N	lo damage on buoy and riding a li	ttle low in water		
Site Sensor Failures	Date Sensors Failed	Why	Field Service	
		Sensors	<b>Observations</b>	
		Failed		

# 2.2 CTD Casts Completed

A Sea-Bird 911plus CTD with dual temperature and conductivity sensors was provided by the NMAO. Temperature and conductivity sensors are calibrated yearly at Sea-Bird and sent in for diagnostics as necessary. A Sea-Bird 12-position carousel and twelve 5-liter Niskin bottles were used to collect water samples for the analysis of salinity.

After the eleventh CTD cast, the CTD winch controller had mechanical problems that could not be repaired at sea. Therefore, only 11 CTD casts were performed on this cruise.

The following outlines the CTD casts completed during the cruise:

CTD Operations			
Nominal Position	Date	Cast #	Comments
5N 180	11/17/2009	KA50011	1000 m
4N 180	11/17/2009	KA50021	1000 m
3N 180	11/17/2009	KA50031	1000 m
2N 180	11/18/2009	KA50041	1000 m
1N 180	11/18/2009	KA50051	1000 m
0 180	11/18/2009	KA50061	1000 m
2n 180	11/19/2009	KA50071	1000 m
8S 170W	11/22/2009	KA50081	1000 m
7S 170W	11/22/2009	KA50091	1000 m
6S 170W	11/23/2009	KA50101	1000 m
5S 170W	11/23/2009	KA50111	1000 m
8S 155W	11/28/2009	KA50121	3000 m
0 155W	12/1/2009	KA50131	3000 m

# 2.3 Ancillary Science Projects Completed on the Cruise

The following outlines the ancillary science work performed in conjunction with the TAO operations on the cruise:

# Pacific Marine Environmental Laboratory (PMEL) Argo Profiling CTD Floats

Three Argo floats were scheduled for deployment on this cruise. The chief scientist verified and briefed the Operations Officer on the deployment positions prior to the start of the cruise. All Argo Float deployments were completed as scheduled.

Questions concerning ARGO Floats should be directed to:

Gregory Johnson, NOAA/PMEL or Elizabeth Steffen, NOAA/PMEL

Tel: (206) 526-6806 Tel: (206) 526-6747

E-mail: pmel\_floats@noaa.gov E-mail: pmel\_floats@noaa.gov

No Argo floats were deployed on this cruise.

### Atlantic Oceanographic and Meteorological Laboratory (AMOL) Surface Drifting Floats

Twelve AOML Surface Drifters were scheduled for deployment on this cruise. The chief scientist verified and briefed the Operations Officer on the deployment positions prior to the start of the cruise. All AOML Surface Drifter deployments were completed as scheduled.

Questions concerning AOML Surface Drifters should be directed to:

Shaun Dolk, NOAA/AOML Global Drifter Center,

Tel: (305) 361-4546

Fax: (305) 361-4436

E-mail: shaun.dolk@noaa.gov

The following outlines the AOML Drifting floats deployed during this cruise:

AOML Floats			
Coordinates	Date	SN#	Comments
1822.016N 16200.021W	11/11/2009	90393	
1525.186N 16603.339W	11/13/2009	90394	
1231.148N 16958.911W	11/14/2009	90391	
0502.348N 17954.134W	11/17/2009	90392	
0328.871N 17950.547W	11/17/2009	90390	
0201.288N 17949.945W	11/18/2009	90388	
0001.872S 17955.244W	11/18/2009	90386	
0158.284S 17952.386W	11/19/2009	90389	
0309.868S 17601.171W	11/20/2009	90387	
0607.158S 17201.484W	11/22/2009	90385	

### PCO2 and Nitrate Mapping System and Nutrient Samples

Thirteen (13) 30ml water samples were collected on this cruise. The chief scientist verified and briefed the Operations Officer on the specifications of the water samples to be collected during CTD casts prior to the start of the cruise. All water samples were collected as scheduled.

Questions concerning Nutrient Samples should be directed to:

Cathy Cosca NOAA/PMEL 7600 Sand Point Way NE Seattle, Washington 98115

Tel: (206) 526-6183

E-mail: cathy.cosca@noaa.gov